

STEP 1
UNCRATE THE ALL PARTS



STEP 2

UNFOLD THE MACHINE CAREFULLY (CRANE OR FORKLIFT MAY REQUIRED)



STEP 3

FOR EASIER ASSEMBLY, PLACE METAL OR WOODEN OBJECT UNDER THE CUTTER BAR AS SHOWN



STEP 4 PREPARE THE MAIN CHASSIS BAR FOR ASSEMBLY



STEP 5
PLACE THE MAIN CHASSIS BAR AS SHOWN

STEP 6
TIGHTEN CONNECTION BOLTS PROPERLY





STEP 7
PREPARE MAIN CHASSIS SUPPORT PIPE



STEP 8



STEP 9
PLACE THE SUPPORT PIPE AT CONNECTION POINT



STEP 10
ASSEMBLY THE SUPPORT PIPE AS SHOWN



STEP 11
ASSEMBLY THE SUPPORT PIPE ON MAIN
CHASSIS BAR WITH U BOLT



STEP 12 PLACE BIG SKID UNDER THE GEARBOX



STEP 13
BIG SKID FRON CONNECTION



STEP 14
BIG SKID REAR CONNECTION



STEP 15
PLACE THREE POINT HITCH



STEP 16 PLACE THE HYDRAULIC KIT ON TOP OF THE THREE POINT HITCH



STEP 17 STEP 18

PLACE THE PINS OF HYRAULIC KIT





STEP 19



STEP 20
ASSEMBLY THE LEFT SIDE DISC AS SHOWN



STEP 21
ASSEMBLY THE RIGHT SIDE DISC AS SHOWN



STEP 22
ASSEMBLY THE PROTECTION COVER







STEP 23
ASSEMBLY SAFETY MECHANISM



STEP 24 CONNECTION OF SAFETY MECHANISM TO THREE POINT HITCH



STEP 24

MOUNT THE PTO SHAFT COVER





STEP 26

STEP 27

PLACE TARPAULIN ON THE PROTECTION COVER



FOLD THE PROTECTION COVER FOR EASIER ASSEMBLY



STEP 28

MINOS DISC MOWER IS READY TO USE

MAKE SURE THAT STRAPS ARE CONNECTED PROPERLY.



